

# **SEG Awards Level 3 Diploma in Welding Techniques and Skills**

---

## **Qualification Guidance**

---

### **Level 3 Diploma – 603/5761/7**

---



This is a live document and as such will be updated when required. It is the responsibility of the approved centre to ensure the most up-to-date version of the Qualification Guide is in use. Any amendments will be published on our website and centres are encouraged to check this site regularly.

## About us

---

At the Skills and Education Group Awards (SEG Awards)<sup>1</sup> we continually invest in high quality qualifications, assessments and services for our chosen sectors. As a UK leading sector specialist we continue to support employers and skills providers to enable individuals to achieve the skills and knowledge needed to raise professional standards across our sectors.

Skills and Education Group has an on-line registration system to help customers register learners on its qualifications, units and exams. In addition it provides features to view exam results, invoices, mark sheets and other information about learners already registered.

The system is accessed via a web browser by connecting to our secure website using a username and password: <https://ors.skillsandeducationgroupawards.co.uk/>

## Sources of Additional Information

---

The Skills and Education Group Awards website <https://skillsandeducationgroupawards.co.uk/> provides access to a wide variety of information.

## Copyright

---

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior permission of the publishers.

This document may be copied by approved centres for the purpose of assessing learners. It may also be copied by learners for their own use.

## Specification Code, Date and Issue Number

---

The specification code is D5711-03

<b>For Skills and Education Awards Use Only</b>			
Issue	Date	Details of change	Section/page
1	1/4/2020	Original document	n/a
2	8/10/2020	Progression Opportunities updated	Page 8

---

<sup>1</sup> SEG Awards is a brand of the Skills and Education Group Awards, a recognised awarding organisation and part of the Skills and Education Group. Any reference to SEG Awards, its registered address, company or charity number should be deemed to mean the Skills and Education Group Awards.

## Contents

---

About us	2
Sources of Additional Information	2
Copyright	2
Specification Code, Date and Issue Number	2
Contents	3
Aims	5
Target Group	5
Qualification Structure	6
Assessment	8
Practice Assessment Material	8
Teaching Strategies and Learning Activities	8
Progression Opportunities	8
Tutor/Assessor Requirements	9
Resource Requirements	9
Language	9
Qualification Summary	10
Unit Details	12
1. Health and Safety in a Fabrication and Welding Environment	12
2. Materials, Science and Calculations for Fabrication and Welding Practice	14
3. Manual Metal-Arc Welding – (Vertical) Low Carbon Steel	20
4. Manual Metal-Arc Welding – (Vertical) Stainless Steel	23
5. Metal-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel	26
6. Metal-Arc Gas Shielded Welding – (Vertical) Stainless Steel	29
7. Metal-Arc Gas Shielded Welding – (Vertical) Aluminium	32
8. Tungsten-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel	35
9. Tungsten-Arc Gas Shielded Welding – (Vertical) Stainless Steel	39
10. Tungsten-Arc Gas Shielded Welding – (Vertical) Aluminium	43
11. Manual Metal-Arc Welding – (Overhead) Low Carbon Steel	47
12. Manual Metal-Arc Welding – (Overhead) Stainless Steel	51
13. Metal-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel	55
14. Metal-Arc Gas Shielded Welding- (Overhead) – Stainless Steel	59
15. Metal-Arc Gas Shielded Welding – (Overhead) Aluminium	63
16. Tungsten-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel	67
17. Tungsten-Arc Gas Shielded Welding – (Overhead) Stainless Steel	72
18. Tungsten-Arc Gas Shielded Welding – (Overhead) Aluminium	76

## Skills and Education Group Awards

19. Thick Plate Welding using Flux Cored Metal-Arc Gas Shielded Welding	80
20. Pipe Welding using Manual Metal-Arc Welding	84
21. Pipe Welding using Metal-Arc Gas Shielded Welding	89
22. Pipe Welding using Tungsten-Arc Gas Shielded Welding	94
Appendices	99
Recognition of Prior Learning, Exemption and Credit Transfer	99
Certification	100
Glossary of Terms	101

## Introduction

- At Skills and Education Group Awards we have updated our suite of Fabrication and Welding qualifications to include the latest fabrication and welding techniques, materials, processes and practices. They are assessed in line with industry demands, which include updated rigorous practical assessments and online on-demand assessments.
- The qualification structures have been developed with the typical learner in mind, to ensure the units contained within them are relevant and facilitate progression, whether that is onto higher levels of learning, employment or specialist fabrication and welding procedures.

The qualifications have been developed in conjunction with academia and industry experts and informed by the work of professional bodies in the fabrication and welding field. At Level 2 and Level 3, the qualifications have been designed to complement the recently developed Apprenticeship Standards in Welding.

This qualification, along with the rest of the suite, has been endorsed by Lincoln Electric.

## Aims

---

Raise a learner's skill level and enhance their underpinning knowledge to promote progression from basic welding and fabrication skills to a more highly developed understanding of equipment functions and how materials behave when subjected to fabrication and welding process.

Educate the learner in the observation of the correct and safe procedures that are paramount in the fabrication and welding industry.

## Target Group

---

The target group includes, but is not limited to:

- young people who are following an apprenticeship programme
- young people who are new entrants to the industry
- adults wishing to specialise or upskill by pursuing single units
- the self-employed

## Qualification Structure

---

### Rules of Combination:

Learners must achieve a minimum of 46 Credits.

11 credits must come from Group A

7 credits must come from Group B

7 credits must come from Group C

7 credits must come from Group D

14 credits must come from Group E

Units	Unit Number	Level	M/O	Credit Value	GLH
Group A					
1. Health and Safety in a Fabrication and Welding Environment	T/618/0753	2	M	3	20
2. Materials, Science and Calculations for Fabrication and Welding Practice	D/616/1291	3	M	8	80
Group B					
3. Manual Metal-Arc Welding – (Vertical) Low Carbon Steel	H/618/0764	3	O	7	60
4. Manual Metal-Arc Welding – (Vertical) Stainless Steel	K/618/0765	3	O	7	60
Group C					
5. Metal-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel	M/618/0766	3	O	7	60
6. Metal-Arc Gas Shielded Welding – (Vertical) Stainless Steel	T/618/0767	3	O	7	60
7. Metal-Arc Gas Shielded Welding – (Vertical) Aluminium	A/618/0768	3	O	7	60
Group D					
8. Tungsten-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel	F/618/0769	3	O	7	60
9. Tungsten-Arc Gas Shielded Welding – (Vertical) Stainless Steel	T/618/0770	3	O	7	60
10. Tungsten-Arc Gas Shielded Welding – (Vertical) Aluminium	A/618/0771	3	O	7	60

Skills and Education Group Awards

Units	Unit Number	Level	M/O	Credit Value	GLH
Group E					
11. Manual Metal-Arc Welding – (Overhead) Low Carbon Steel	H/618/0778	3	0	7	60
12. Manual Metal-Arc Welding – (Overhead) Stainless Steel	D/618/0780	3	0	7	60
13. Metal-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel	H/618/0781	3	0	7	60
14. Metal-Arc Gas Shielded Welding – (Overhead) Stainless Steel	K/618/0782	3	0	7	60
15. Metal-Arc Gas Shielded Welding – (Overhead) Aluminium	M/618/0783	3	0	7	60
16. Tungsten-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel	A/618/0785	3	0	7	60
17. Tungsten-Arc Gas Shielded Welding – (Overhead) Stainless Steel	F/618/0786	3	0	7	60
18. Tungsten-Arc Gas Shielded Welding – (Overhead) Aluminium	J/618/0787	3	0	7	60
19. Thick Plate Welding using Flux Cored Metal-Arc Gas Welding	T/616/1300	3	0	7	60
20. Pipe Welding using Manual Metal-Arc Welding	L/618/0788	3	0	7	60
21. Pipe Welding using Metal-Arc Gas Shielded Welding	R/618/0789	3	0	7	60
22. Pipe Welding using Tungsten-Arc Gas Shielded Welding	J/618/0790	3	0	7	60

GLH: **400 hours**

TQT: **460 hours**

Credit value: **46**

## Assessment

---

In order to successfully achieve this qualification a learner must fully meet all of the learning outcomes. This is done by completing the Skills and Education Group Awards' practical and online multiple-choice assessments.

All centres are required to have internal quality assurance processes in place. Assessment workbooks are available on the Skills and Education Group Awards website for learners to complete to form the internal assessment requirements for each unit. The practical tasks in the workbooks are graded at a pass, merit or distinction.

The Science and Calculations unit is assessed via an externally set and externally assessed multiple choice question (MCQ) assessment. The examination provides the grade for this unit at a:

- Pass – 60%
- Merit – 70% or
- Distinction – 80%.

The overall qualification is graded as pass/fail however, unit achievements at pass, merit or distinction are shown on the qualification transcript.

For further information around assessment including reasonable adjustments and special considerations please review the Access to Assessment Policy here:

<https://skillsandeducationgroupawards.co.uk/policies-and-procedures/>

## Practice Assessment Material

---

Skills and Education Group Awards will make paper-based, multiple choice, practice tests available for learners prior to undertaking the online knowledge test. These questions will be of a comparable level and cover the same subject areas as listed above in the 'assessment' section, but they will not be the same questions as those presented during the online knowledge test.

## Teaching Strategies and Learning Activities

---

Centres should adopt a delivery approach which supports the development of all individuals. The aims and aspirations of all the learners, including those with identified special needs or learning difficulties/disabilities, should be considered and appropriate support mechanisms put in place.

## Progression Opportunities

---

Learners who successfully achieve this qualification could progress into employment within a fabrication and welding environment or a manufacturing environment.

## **Tutor/Assessor Requirements**

---

Skills and Education Group Awards require those involved in the assessment process to be suitably experienced and/or qualified. In general terms, this usually means that the Tutor/Assessor must be knowledgeable in the subject/occupational area to at least the level they are delivering/assessing at.

Those responsible for Internal Quality Assurance (IQA) must be knowledgeable of the subject/occupational area to a suitable level to carry out accurate quality assurance practices and processes.

## **Resource Requirements**

---

Centres must provide access to sufficient equipment in the centre or workplace to ensure learners have the opportunity to cover all of the practical activities.

For external assessments the examination should be conducted at the Centre where the course delivery has taken place and should be carried out in accordance with the examination requirements of Skills and Education Group Awards.

## **Language**

---

These specifications and associated assessment materials are in English only.

## Qualification Summary

---

<b>SEG Awards SEG Level 3 Diploma in Welding Techniques and Skills</b>								
Qualification Number	603/5761/7							
Regulated	The qualification identified above is regulated by Ofqual, Qualifications Wales and CCEA Regulation.							
Assessment	<ul style="list-style-type: none"> <li>• Internally set, internally assessed</li> <li>• Externally set, internally assessed</li> <li>• Externally set, externally assessed</li> <li>• Internal and external moderation</li> </ul>							
Grading	Pass							
Operational Start Date	01/09/2020							
Review Date	01/09/2023							
Skills and Education Group Awards Sector	Engineering							
SSA Sector	4.1 Engineering							
Contact	See the Skills and Education Group Awards website for Customer Support Officer responsible for these qualifications.							
Qualification Purpose	C. Prepare for employment C1. Prepare for employment in a broad occupational area							
Entry Requirements	There are no formal pre-requisites for entry onto this qualification. Each centre is required to notify the awarding body of its policies on access and equality of opportunity. Within the parameters of these policies, a centre is expected to recruit with integrity on the basis of a learner's ability to contribute to and successfully complete the qualification.							
Age Range	Pre 16		16 - 18	✓	18+	✓	19+	✓

## Skills and Education Group Awards

Recommended GLH	Level 3 Diploma – 400
Recommended TQT	Level 3 Diploma – 460
Credit Value	Level 3 Diploma – 46
Learning Aims Reference	See Learning Aim Reference Service (LARS) website: <a href="https://data.gov.uk/dataset/learning-aim-reference-service">https://data.gov.uk/dataset/learning-aim-reference-service</a>
Type of Funding Available	See Learning Aim Reference Service (LARS) website
Qualification Fee	See Skills and Education Group Awards website for current fees and charges.
Additional Information	See Skills and Education Group Awards website for resources available for this qualification.

## Unit Details

### 1. Health and Safety in a Fabrication and Welding Environment

Unit Reference	T/618/0753
Level	2
Credit Value	3
Guided Learning Hours	20
Unit Summary	<p>In this unit, learners will find out about health and safety legislation, and the application of safe working practices within a workplace. They will explore hazards and precautions, signs and symbols and basic safety procedures.</p> <p>Health and Safety must be an integral part of every learner's programme. It is expected that the outcomes listed will be integrated as appropriate into each unit of this qualification.</p> <p>Skills and Education Group Awards has produced a workbook which learners can use to provide evidence of achievement against the learning outcomes and assessment criteria. The workbook is available on the SEG website.</p> <p>Skills and Education Group Awards also provides Learner Achievement Checklists to record achievement. These are also available on SEG's website.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria</p> <p>The learner can:</p>
1. Know about health and safety responsibilities	<p>1.1. Identify the basic responsibilities of employer and employee with regard to Health and Safety at Work Act 1974 (where legislation, regulations do not apply in the jurisdiction, relevant ones should be applied)</p> <p>1.2 Identify the statutory requirements and legislation of the Health and Safety at Work in a fabrication and welding work environment</p>

## Skills and Education Group Awards

<p>2. Know how to avoid risks in a fabrication and welding work environment</p>	<p>2.1. Identify and describe where potential health and safety hazards may occur within a fabrication and welding work environment</p> <p>2.2 Identify potential hazards and the necessary precautions in a fabrication and welding environment for each of the following</p> <ul style="list-style-type: none"> <li>• when moving and handling materials</li> <li>• when using hand and power tools</li> <li>• when using thermal processes</li> </ul>
<p>3. Undertake a risk assessment of fabrication and welding work environment</p>	<p>3.1 Identify the five steps of a risk assessment</p> <p>3.2 Conduct a risk assessment of a fabrication and welding work environment</p> <p>3.3 Report findings to an appropriate person in line with organisational requirements</p>
<p>4. Know how to protect themselves in a work environment</p>	<p>4.1 State reasons why protective clothing and equipment should be worn</p> <p>4.2 Identify common safety guards, screens and fences within a workshop situation</p> <p>4.3 Locate fire extinguishers, emergency switches and exits in the work environment</p> <p>4.4 Describe how waste materials should be dealt with to comply with current laws and regulations</p>
<p>5. Know about accident and emergency procedures</p>	<p>5.1 Describe their organisational accident and emergency procedures in relation to</p> <ul style="list-style-type: none"> <li>• injury to self or others</li> <li>• fire</li> <li>• malfunctions of equipment</li> <li>• problems with hazardous substances</li> </ul>
<p>6. Understand safety signs</p>	<p>6.1 Identify safety signs within the following groups</p> <ul style="list-style-type: none"> <li>• mandatory</li> <li>• warning</li> <li>• safe condition</li> <li>• prohibited</li> </ul>

## 2. Materials, Science and Calculations for Fabrication and Welding Practice

---

Unit Reference	D/616/1291
Level	3
Credit Value	8
Guided Learning Hours	80
Unit Summary	<p>This is a mandatory unit which will be assessed by a 40 question on-line multi-choice question (MCQ) assessment.</p> <p>Learners will gain an understanding of various topics associated with the related aspects of welding and fabrication.</p> <p>The main areas or key focus points are materials, science, calculations and quality control of welding and fabrication operations.</p> <p>There is no practical requirement for this unit, however, observation of demonstrations concerning various aspects of the assessment criteria carried out in the workshop or laboratory is to be encouraged.</p>

Skills and Education Group Awards

Learning Outcomes The learner will:	Assessment Criteria The learner can:
<p>1. Identify a range of materials used in engineering</p>	<p>1.1. Identify the characteristics of materials used in engineering, to include:</p> <ul style="list-style-type: none"> <li>• ferrous metals</li> <li>• non-ferrous metals</li> <li>• thermoplastics</li> <li>• thermosetting plastics</li> <li>• ceramics</li> <li>• composites</li> </ul> <p>1.2. Identify an engineering application for each material listed in 1.1</p> <p>1.3. Identify the approximate carbon percentage of:</p> <ul style="list-style-type: none"> <li>• low carbon steel</li> <li>• medium carbon steel</li> <li>• high carbon steel</li> </ul> <p>1.4. Identify common alloying elements added to steel</p> <p>1.5. Describe the changes to the mechanical properties of steels by the addition of alloying elements</p> <p>1.6. Identify typical compositions of common engineering materials, to include</p> <ul style="list-style-type: none"> <li>• stainless steel</li> <li>• brass</li> <li>• bronze</li> <li>• duralumin</li> </ul>
<p>2. Know about the crystalline structure of weld deposits in steels</p>	<p>2.1. Identify the different types of crystalline structure found in both single pass and multi pass weld deposits found in welded joints in steels, to include:</p> <ul style="list-style-type: none"> <li>• parent material</li> <li>• weld deposit</li> <li>• heat affected zone (HAZ)</li> </ul> <p>2.2. Identify the stages of recrystallisation and grain growth in steel</p>

Skills and Education Group Awards

<p>3. Know about heat treatments and the effects of heat on materials</p>	<p>3.1. Identify the heat treatment process of materials, to include:</p> <ul style="list-style-type: none"> <li>• annealing</li> <li>• normalising</li> <li>• hardening</li> <li>• tempering</li> <li>• stress relieving</li> </ul> <p>3.2. Describe how the properties of a material can be changed by the application of a heat treatment process</p> <p>3.3. Describe the effects of hot and cold working on the mechanical properties of steels</p> <p>3.4. Identify the purpose of using pre and post heating on welded joints in steels</p> <p>3.5. Describe the effects of welding and cooling rates on the structure and mechanical properties of welded joints</p>
<p>4. Know about the mechanical testing of materials and the properties of materials</p>	<p>4.1. Identify methods of mechanically testing materials, to include:</p> <ul style="list-style-type: none"> <li>• tensile testing</li> <li>• hardness testing (Brinell, Vickers and Rockwell)</li> <li>• charpy/izod testing</li> <li>• fatigue testing</li> </ul> <p>4.2. Define the terms associated with the properties of materials, to include:</p> <ul style="list-style-type: none"> <li>• work hardening</li> <li>• weldability of materials</li> <li>• hardenability</li> <li>• cold working</li> </ul> <p>4.3. Identify the effects when different types of forces are applied to a material, to include:</p> <ul style="list-style-type: none"> <li>• tensile force</li> <li>• compressive force</li> <li>• shear force</li> <li>• torsion</li> </ul>
<p>5. Understand the structure and state of matter</p>	<p>5.1. Recognise the three states of matter</p> <p>5.2. Identify the basic structure of matter, to include:</p> <ul style="list-style-type: none"> <li>• atoms</li> <li>• molecules</li> <li>• elements</li> <li>• compounds</li> <li>• mixtures</li> </ul> <p>5.3. Be able to give examples of alloys, elements, compounds and mixtures</p>

Skills and Education Group Awards

<p>6. Understand the units used in the SI system</p>	<p>6.1. Recognise the SI units for engineering applications, to include:</p> <ul style="list-style-type: none"> <li>• force</li> <li>• energy</li> <li>• heat</li> <li>• time</li> <li>• length</li> <li>• area</li> <li>• volume</li> <li>• mass</li> <li>• electrical current</li> <li>• gas pressure</li> </ul>
<p>7. Understand the electrical principles and conditions of welding processes</p>	<p>7.1. Define:</p> <ul style="list-style-type: none"> <li>• open circuit voltage (OCV)</li> <li>• arc voltage</li> <li>• welding current</li> </ul> <p>7.2. Identify the effects of increasing/decreasing the arc length when MMA welding on the:</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• arc voltage</li> </ul> <p>7.3. Identify the characteristics of a welding power source, to include flat and drooping types</p> <p>7.4. Identify welding processes that use flat or drooping characteristic type power sources</p> <p>7.5. Explain the terms associated with welding power sources, to include:</p> <ul style="list-style-type: none"> <li>• duty cycles</li> <li>• single and three phase systems</li> <li>• tapped reactor</li> <li>• moving core reactor</li> </ul>

Skills and Education Group Awards

<p>8. Be able to use calculations relating to fabrication and welding activities</p>	<p>8.1. Calculate volume and surface areas applicable to fabricated and welded assemblies</p> <p>8.2. Calculate the cost of welding, to include:</p> <ul style="list-style-type: none"> <li>• purchase of equipment</li> <li>• cost of consumables</li> <li>• purchase of materials</li> <li>• cost of labour</li> </ul> <p>8.3. Calculate total length of welding required for a fabricated assembly</p> <p>8.4. Calculate unknown angles and side lengths in right angled triangles using trigonometry</p> <p>8.5. Calculate unknown side lengths in right angled triangles using the Pythagoras theory</p> <p>8.6. Calculate the length of flat section required to produce a cylinder of a given diameter using the mean or neutral line</p> <p>8.7. Calculate bending allowances when producing bends/folds in material</p>
<p>9. Know about the problems associated with the manufacture of fabricated and welded assemblies</p>	<p>9.1. Identify different types of distortion that can occur in welded assemblies, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>9.2. Identify methods used for the control of distortion in welded assemblies</p> <p>9.3. Describe the importance of selecting and using the correct joint preparation for a given joint type</p> <p>9.4. Describe typical welding defects specific to the welding processes listed:</p> <ul style="list-style-type: none"> <li>• MMA welding</li> <li>• MAGS welding</li> <li>• TAG welding</li> </ul> <p>9.5. Identify the problems associated with the conditions found in a completed welded joint, to include:</p> <ul style="list-style-type: none"> <li>• residual stress</li> <li>• corrosion</li> <li>• shock loading</li> <li>• distortion</li> </ul>

## Skills and Education Group Awards

<p>10. Know the importance of quality assurance in fabrication and welding activities</p>	<p>10.1. Describe the application and procedures to be followed when carrying out non-destructive testing (NDT) of welded joints, to include:</p> <ul style="list-style-type: none"><li>• dye penetrant testing</li><li>• magnetic particle testing</li><li>• ultrasonic flaw detection</li><li>• radiography</li></ul> <p>10.2. Identify the limitations of using the NDT methods listed in 10.1</p> <p>10.3. Identify the importance of carrying out quality control checks on welding consumables</p> <p>10.4. Identify the application and use of quality control documentation, to include:</p> <ul style="list-style-type: none"><li>• welding procedure specification (WPS)</li><li>• Inspection report for welding</li><li>• certificates of conformity (consumables)</li></ul>
-------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

### 3. Manual Metal-Arc Welding – (Vertical) Low Carbon Steel

Unit References	H/618/0764
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering manual metal-arc (MMA) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualification in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the MMA welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> </ul>

## Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for MMA welding activities</p>	<p>2.1. Describe the function of the equipment used in MMA welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• invertors</li> <li>• welding lead cable</li> <li>• welding return cable</li> <li>• secondary earth and connector</li> <li>• electrode holder</li> <li>• cable clamp</li> <li>• low voltage safety devices (LVSD)</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used when using the MMA welding process</p>	<p>3.1. Identify a range of electrodes that are used for the MMA welding process, to include:</p> <ul style="list-style-type: none"> <li>• general purpose</li> <li>• low hydrogen (basic)</li> <li>• positional</li> </ul> <p>3.2. State the function of the flux coating on electrodes</p> <p>3.3. Describe the effects of incorrect storage of electrodes</p> <p>3.4. State the effect of using damaged electrodes when carrying out welding activities</p>
<p>4. Understand the welding parameters used when carrying out MMA welding in the vertical welding (PF/PG) position</p>	<p>4.1. Identify and select the welding parameters to be used when welding materials in the vertical welding position (PF/PG), to include:</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• OCV (open circuit voltage)</li> <li>• electrode slope and tilt angles</li> <li>• arc length</li> <li>• speed of travel</li> <li>• electrode polarity</li> </ul>

## Skills and Education Group Awards

<p>5. Know about material preparation and the setting up of MMA welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the MMA welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MMA welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>
<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on the completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the MMA welding process</p>	<p>8.1. Identify and describe typical defects found in MMA welded joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions (slag)</li> <li>• undercut</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 4. Manual Metal-Arc Welding – (Vertical) Stainless Steel

Unit References	K/618/0765
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering manual metal-arc (MMA) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualification in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the MMA welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> </ul>

## Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for MMA welding activities</p>	<p>2.1. Describe the function of the equipment used in MMA welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• invertors</li> <li>• welding lead cable</li> <li>• welding return cable</li> <li>• secondary earth and connector</li> <li>• electrode holder</li> <li>• cable clamp</li> <li>• low voltage safety devices (LVSD)</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used when using the MMA welding process</p>	<p>3.1. Identify a range of electrodes that are used for the MMA welding process, to include:</p> <ul style="list-style-type: none"> <li>• general purpose</li> <li>• low hydrogen (basic)</li> <li>• positional</li> </ul> <p>3.2. State the function of the flux coating on electrodes</p> <p>3.3. Describe the effects of incorrect storage of electrodes</p> <p>3.4. State the effect of using damaged electrodes when carrying out welding activities</p>
<p>4. Understand the welding parameters used when carrying out MMA welding in the vertical welding (PF/PG) position</p>	<p>4.1. Identify and select the welding parameters to be used when welding materials in the vertical welding position (PF/PG), to include:</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• OCV (open circuit voltage)</li> <li>• electrode slope and tilt angles</li> <li>• arc length</li> <li>• speed of travel</li> <li>• electrode polarity</li> </ul>

## Skills and Education Group Awards

<p>5. Know about material preparation and the setting up of MMA welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the MMA welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MMA welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>
<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on the completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the MMA welding process</p>	<p>8.1. Identify and describe typical defects found in MMA welded joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions (slag)</li> <li>• undercut</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 5. Metal-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel

Unit References	M/618/0766
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering metal-arc gas shielded (MAGS) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualifications in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the MAGS welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> </ul>

Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for MAGS welding activities</p>	<p>2.1. Describe the function of the equipment used in the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• contact tip</li> <li>• shroud/nozzle</li> <li>• wire feed mechanism</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used when using the MAGS welding process</p>	<p>3.1. Identify a range of electrode wires that are used for the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• copper coated</li> </ul> <p>3.2. Describe the effects of incorrect storage of electrode wires</p> <p>3.3. Recognise the effect of using damaged electrode wires when carrying out welding activities</p> <p>3.4. Identify the shielding gas/es used in MAGS welding</p> <p>3.5. Identify the function of the shielding gas used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying MAGS welding in the vertical welding (PF/PG) position</p>	<p>4.1. Recognise the different modes of metal transfer used in MAGS welding</p> <p>4.2. Identify and select the welding parameters to be used when welding materials greater than 6 mm in thickness in the vertical welding position (PF/PG).</p> <ul style="list-style-type: none"> <li>• mode of metal transfer</li> <li>• welding current</li> <li>• arc voltage</li> <li>• torch slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• wire speed</li> <li>• speed of travel</li> </ul>

## Skills and Education Group Awards

<p>5. Know about material preparation and the setting up of MAGS welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>
<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify and describe typical defects found in the MAGS welding process joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions</li> <li>• undercut</li> <li>• lack of fusion</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 6. Metal-Arc Gas Shielded Welding – (Vertical) Stainless Steel

Unit References	T/618/0767
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering metal-arc gas shielded (MAGS) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualifications in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the MAGS welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> </ul>

Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for MAGS welding activities</p>	<p>2.1. Describe the function of the equipment used in the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• contact tip</li> <li>• shroud/nozzle</li> <li>• wire feed mechanism</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used when using the MAGS welding process</p>	<p>3.1. Identify a range of electrode wires that are used for the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• copper coated</li> </ul> <p>3.2. Describe the effects of incorrect storage of electrode wires</p> <p>3.3. Recognise the effect of using damaged electrode wires when carrying out welding activities</p> <p>3.4. Identify the shielding gas/es used in MAGS welding</p> <p>3.5. Identify the function of the shielding gas used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying MAGS welding in the vertical welding (PF/PG) position</p>	<p>4.1. Recognise the different modes of metal transfer used in MAGS welding</p> <p>4.2. Identify and select the welding parameters to be used when welding materials greater than 6 mm in thickness in the vertical welding position (PF/PG).</p> <ul style="list-style-type: none"> <li>• mode of metal transfer</li> <li>• welding current</li> <li>• arc voltage</li> <li>• torch slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• wire speed</li> <li>• speed of travel</li> </ul>

Skills and Education Group Awards

<p>5. Know about material preparation and the setting up of MAGS welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>
<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify and describe typical defects found in the MAGS welding process joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions</li> <li>• undercut</li> <li>• lack of fusion</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 7. Metal-Arc Gas Shielded Welding – (Vertical) Aluminium

Unit References	A/618/0768
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering metal-arc gas shielded (MAGS) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualifications in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the MAGS welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> </ul>

Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for MAGS welding activities</p>	<p>2.1. Describe the function of the equipment used in the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• contact tip</li> <li>• shroud/nozzle</li> <li>• wire feed mechanism</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used when using the MAGS welding process</p>	<p>3.1. Identify a range of electrode wires that are used for the MAGS welding process, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• copper coated</li> </ul> <p>3.2. Describe the effects of incorrect storage of electrode wires</p> <p>3.3. Recognise the effect of using damaged electrode wires when carrying out welding activities</p> <p>3.4. Identify the shielding gas/es used in MAGS welding</p> <p>3.5. Identify the function of the shielding gas used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying MAGS welding in the vertical welding (PF/PG) position</p>	<p>4.1. Recognise the different modes of metal transfer used in MAGS welding</p> <p>4.2. Identify and select the welding parameters to be used when welding materials greater than 6 mm in thickness in the vertical welding position (PF/PG).</p> <ul style="list-style-type: none"> <li>• mode of metal transfer</li> <li>• welding current</li> <li>• arc voltage</li> <li>• torch slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• wire speed</li> <li>• speed of travel</li> </ul>

## Skills and Education Group Awards

<p>5. Know about material preparation and the setting up of MAGS welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>
<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify and describe typical defects found in the MAGS welding process joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions</li> <li>• undercut</li> <li>• lack of fusion</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 8. Tungsten-Arc Gas Shielded Welding – (Vertical) Low Carbon Steel

Unit References	F/618/0769
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering tungsten inert gas shielded (TAG) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualification in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the TAG welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> <li>• with hazards from using high frequency units</li> </ul>

## Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for TAG welding activities</p>	<p>2.1. Describe the function of the equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• inverter</li> <li>• high frequency units</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• tungsten</li> <li>• collet</li> <li>• shroud</li> <li>• cooling system</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used with the TAG welding process</p>	<p>3.1. Identify a range of tungsten electrodes that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> <li>• preparation of electrode tip (shape/dimensions)</li> </ul> <p>3.2. Identify a range of filler wires that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> </ul> <p>3.3. Describe the effects of incorrect storage of tungsten electrode and filler wires</p> <p>3.4. State the effect of using damaged tungsten electrode and filler wires when carrying out welding activities</p> <p>3.5. Identify the shielding gas/es used in TAG welding</p> <p>3.6. Identify the function of the shielding gas used in TAG welding</p>

## Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out TAG welding in the vertical welding (PF/PG) position</p>	<p>4.1. Identify and select the welding parameters to be used when welding in the vertical welding position (PF/PG):</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• torch slope and tilt angles</li> <li>• filler wire slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• arc length</li> <li>• speed of travel</li> </ul> <p>4.2. Identify the use of autogenous techniques when using the TAG welding process</p>
<p>5. Know about material preparation and the setting up of TAG welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> <li>• chills</li> <li>• weld sequence</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>

## Skills and Education Group Awards

<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"><li>• face bend</li><li>• root bend</li><li>• fracture test</li></ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify and describe typical defects found in the TAG welding process joints, to include:</p> <ul style="list-style-type: none"><li>• cracks</li><li>• inclusions</li><li>• undercut</li><li>• lack of fusion</li><li>• arc craters</li><li>• porosity</li><li>• lack of penetration</li></ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 9. Tungsten-Arc Gas Shielded Welding – (Vertical) Stainless Steel

Unit References	T/618/0770
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering tungsten inert gas shielded (TAG) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualification in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the TAG welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> <li>• with hazards from using high frequency units</li> </ul>

Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for TAG welding activities</p>	<p>2.1. Describe the function of the equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• inverter</li> <li>• high frequency units</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• tungsten</li> <li>• collet</li> <li>• shroud</li> <li>• cooling system</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used with the TAG welding process</p>	<p>3.1. Identify a range of tungsten electrodes that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> <li>• preparation of electrode tip (shape/dimensions)</li> </ul> <p>3.2. Identify a range of filler wires that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> </ul> <p>3.3. Describe the effects of incorrect storage of tungsten electrode and filler wires</p> <p>3.4. State the effect of using damaged tungsten electrode and filler wires when carrying out welding activities</p> <p>3.5. Identify the shielding gas/es used in TAG welding</p> <p>3.6. Identify the function of the shielding gas used in TAG welding</p>

Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out TAG welding in the vertical welding (PF/PG) position</p>	<p>4.1. Identify and select the welding parameters to be used when welding in the vertical welding position (PF/PG):</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• torch slope and tilt angles</li> <li>• filler wire slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• arc length</li> <li>• speed of travel</li> </ul> <p>4.2. Identify the use of autogenous techniques when using the TAG welding process</p>
<p>5. Know about material preparation and the setting up of TAG welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> <li>• chills</li> <li>• weld sequence</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>

## Skills and Education Group Awards

<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"><li>• face bend</li><li>• root bend</li><li>• fracture test</li></ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify and describe typical defects found in the TAG welding process joints, to include:</p> <ul style="list-style-type: none"><li>• cracks</li><li>• inclusions</li><li>• undercut</li><li>• lack of fusion</li><li>• arc craters</li><li>• porosity</li><li>• lack of penetration</li></ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 10. Tungsten-Arc Gas Shielded Welding – (Vertical) Aluminium

Unit References	A/618/0771
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>This unit covering tungsten inert gas shielded (TAG) welding is designed to further the skills of the learner who has satisfactorily completed and achieved a level 2 qualification in fabrication and welding practice.</p> <p>Learners will further develop skills in the theory of safe working practice and the theoretical aspects of technology associated with this particular welding process.</p> <p>For this qualification all welding is to be carried out in the vertical welding position (PF/PG) covering a range of welded joints. Both the fillet weld and butt joint will be tested to ensure that they are structurally sound.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Understand health and safety legislation and follow safe working practices	<p>1.1. Identify the responsibilities of both the employer and the employee when complying with the Health and Safety at Work Act 1974</p> <p>1.2. Identify the use of current legislation, to include:</p> <ul style="list-style-type: none"> <li>• COSHH (Control of Substances Hazardous to Health)</li> <li>• PUWER (Provision and Use of Work Equipment)</li> <li>• RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations)</li> </ul> <p>1.3. Identify the use of a risk assessment procedure</p> <p>1.4. Identify safe working practices when using the TAG welding process, to include working:</p> <ul style="list-style-type: none"> <li>• in a confined space</li> <li>• at an height above 2 metres</li> <li>• with containers that have held chemicals or flammable liquids</li> <li>• in damp or wet conditions</li> <li>• with hazards from using high frequency units</li> </ul>

Skills and Education Group Awards

<p>2. Be able to identify and use, in a safe manner, equipment used for TAG welding activities</p>	<p>2.1. Describe the function of the equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• rectifier</li> <li>• inverter</li> <li>• high frequency units</li> <li>• welding lead cable and clamp</li> <li>• welding return cable and clamp</li> <li>• secondary earth and connector</li> <li>• torch</li> <li>• tungsten</li> <li>• collet</li> <li>• shroud</li> <li>• cooling system</li> <li>• gas supply, regulator and flow meter</li> </ul> <p>2.2. Identify suitable maintenance checks that would be required on the items listed in 2.1</p> <p>2.3. State the procedures to be followed for the safe storage of welding equipment when the welding activity has been completed</p>
<p>3. Be able to identify consumables used with the TAG welding process</p>	<p>3.1. Identify a range of tungsten electrodes that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> <li>• preparation of electrode tip (shape/dimensions)</li> </ul> <p>3.2. Identify a range of filler wires that are used for the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• types used</li> <li>• size (diameter)</li> <li>• alloying additions</li> </ul> <p>3.3. Describe the effects of incorrect storage of tungsten electrode and filler wires</p> <p>3.4. State the effect of using damaged tungsten electrode and filler wires when carrying out welding activities</p> <p>3.5. Identify the shielding gas/es used in TAG welding</p> <p>3.6. Identify the function of the shielding gas used in TAG welding</p>

Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out TAG welding in the vertical welding (PF/PG) position</p>	<p>4.1. Identify and select the welding parameters to be used when welding in the vertical welding position (PF/PG):</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• torch slope and tilt angles</li> <li>• filler wire slope and tilt angles</li> <li>• shielding gas flow rate</li> <li>• arc length</li> <li>• speed of travel</li> </ul> <p>4.2. Identify the use of autogenous techniques when using the TAG welding process</p>
<p>5. Know about material preparation and the setting up of TAG welding equipment</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded</p> <p>5.2. Identify terms associated with welding preparations, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.3. Describe the application of distortion control techniques, to include:</p> <ul style="list-style-type: none"> <li>• pre-setting</li> <li>• restraint</li> <li>• joint geometry</li> <li>• chills</li> <li>• weld sequence</li> </ul> <p>5.4. Be able to follow instructions given on a WPS (Welding Procedure Sheet)</p>
<p>6. Be able to complete welds in the vertical welding position (PF/PG) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on low carbon steel or stainless steel or aluminium</p> <ul style="list-style-type: none"> <li>• tee fillet (PF)</li> <li>• butt (PF)</li> <li>• open outside corner (PF or PG)</li> <li>• lap joint (PF or PG)</li> </ul>

Skills and Education Group Awards

<p>7. Know how to carry out visual inspection and destructive tests on completed welds</p>	<p>7.1. Carry out visual inspection of completed welds</p> <p>7.2. Prepare and carry out nick break tests on completed fillet welds</p> <p>7.3. Prepare and carry out destructive tests on completed butt welds, to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul> <p>7.4. Record the results of the weld examination as detailed in 7.1, 7.2 and 7.3</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify and describe typical defects found in the TAG welding process joints, to include:</p> <ul style="list-style-type: none"> <li>• cracks</li> <li>• inclusions</li> <li>• undercut</li> <li>• lack of fusion</li> <li>• arc craters</li> <li>• porosity</li> <li>• lack of penetration</li> </ul> <p>8.2. Identify possible causes of the defects listed in 8.1</p>

## 11. Manual Metal-Arc Welding – (Overhead) Low Carbon Steel

Unit References	H/618/0778
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out MMA welding activities	<p>1.1. Identify the roles of various organisations involved with safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose for and typical contents of an organisations' Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MMA welding process</p>	<p>2.1. Identify the different power sources used in MMA welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• inverter</li> </ul> <p>2.2. Describe features of the power sources as listed in 2.1, to include:</p> <ul style="list-style-type: none"> <li>• type of current produced (AC/DC)</li> <li>• maintenance requirements</li> <li>• portability</li> <li>• suitable applications</li> </ul> <p>2.3. Identify the advantages and limitations of using both alternating current (AC) and direct current (DC)</p> <p>2.4. Describe how the electrical features listed affect the MMA welding process:</p> <ul style="list-style-type: none"> <li>• change of polarity when using direct current (DC)</li> <li>• current control (tapped, moving core and moving coil)</li> <li>• duty cycle of the power source</li> <li>• drooping characteristic feature</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables used in the MMA welding process</p>	<p>3.1. Describe the importance of correct storage conditions for electrodes, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrodes, to include:</p> <ul style="list-style-type: none"> <li>• cellulosic</li> <li>• rutile</li> <li>• basic (low hydrogen)</li> </ul> <p>3.3. Describe the reasons why basic (low hydrogen) electrodes require special conditions when being stored prior to use</p> <p>3.4. Describe the effects of using damaged or damp electrodes</p>

Skills and Education Group Awards

	<p>3.5. Identify the functions of:</p> <ul style="list-style-type: none"> <li>• flux coating on the electrode</li> <li>• slag covering on the weld deposit</li> </ul>
<p>4. Understand the welding parameters used when carrying out MMA welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• OCV (open circuit voltage)</li> <li>• electrode slope and tilt angles</li> <li>• arc length</li> <li>• speed of travel</li> <li>• electrode polarity</li> </ul>
<p>5. Know about material preparation and distortion control when using MMA welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Describe the significance of residual stress found in welded joint</p> <p>5.5. Identify the main causes of distortion in welded joints</p> <p>5.6. Identify methods used to control distortion in welded joints</p>

## Skills and Education Group Awards

<p>6. Be able to complete welds in the overhead welding position (PE) using the MMA welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MMA welding process on low carbon steel.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt weld(PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul>
<p>7. Know about defects found in welds produced by the MMA welding process</p>	<p>7.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the MMA welding process</p> <p>7.2. Identify the use of aids when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>
<p>8. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>8.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>8.2. Describe the importance of carrying out quality control checks on consumables used in MMA welding activities</p> <p>8.3. Describe the range and purpose of destructive workshop tests used on welded joints</p> <p>8.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>8.5. Identify the importance of documenting weld inspection activities</p>

## 12. Manual Metal-Arc Welding – (Overhead) Stainless Steel

Unit References	D/618/0780
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out MMA welding activities	<p>1.1. Identify the roles of various organisations involved with safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose for and typical contents of an organisations' Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MMA welding process</p>	<p>2.1. Identify the different power sources used in MMA welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• inverter</li> </ul> <p>2.2. Describe features of the power sources as listed in 2.1, to include:</p> <ul style="list-style-type: none"> <li>• type of current produced (AC/DC)</li> <li>• maintenance requirements</li> <li>• portability</li> <li>• suitable applications</li> </ul> <p>2.3. Identify the advantages and limitations of using both alternating current (AC) and direct current (DC)</p> <p>2.4. Describe how the electrical features listed affect the MMA welding process:</p> <ul style="list-style-type: none"> <li>• change of polarity when using direct current (DC)</li> <li>• current control (tapped, moving core and moving coil)</li> <li>• duty cycle of the power source</li> <li>• drooping characteristic feature</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables used in the MMA welding process</p>	<p>3.1. Describe the importance of correct storage conditions for electrodes, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrodes, to include:</p> <ul style="list-style-type: none"> <li>• cellulosic</li> <li>• rutile</li> <li>• basic (low hydrogen)</li> </ul> <p>3.3. Describe the reasons why basic (low hydrogen) electrodes require special conditions when being stored prior to use</p> <p>3.4. Describe the effects of using damaged or damp electrodes</p>

Skills and Education Group Awards

	<p>3.5. Identify the functions of:</p> <ul style="list-style-type: none"> <li>• flux coating on the electrode</li> <li>• slag covering on the weld deposit</li> </ul>
<p>4. Understand the welding parameters used when carrying out MMA welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding stainless steel in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding current</li> <li>• OCV (open circuit voltage)</li> <li>• electrode slope and tilt angles</li> <li>• arc length</li> <li>• speed of travel</li> <li>• electrode polarity</li> </ul>
<p>5. Know about material preparation and distortion control when using MMA welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Describe the significance of residual stress found in welded joint</p> <p>5.5. Identify the main causes of distortion in welded joints</p> <p>5.6. Identify methods used to control distortion in welded joints</p>
<p>6. Be able to complete welds in the overhead welding position (PE) using the MMA welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MMA welding process on stainless steel.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt weld(PE)</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> </ul>
<p>7. Know about defects found in welds produced by the MMA welding process</p>	<p>7.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the MMA welding process</p> <p>7.2. Identify the use of aids when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>
<p>8. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>8.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>8.2. Describe the importance of carrying out quality control checks on consumables used in MMA welding activities</p> <p>8.3. Describe the range and purpose of destructive workshop tests used on welded joints</p> <p>8.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>8.5. Identify the importance of documenting weld inspection activities</p>

## 13. Metal-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel

Unit References	H/618/0781
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying MAGS welding activities	<p>1.1. Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MAGS welding process</p>	<p>2.1. Identify the power sources used in MAGS welding</p> <p>2.2. Describe the principle of the self-adjusting arc mechanism as applied to MAGS welding</p> <p>2.3. Describe how inductance can regulate the quality of the weld deposit</p> <p>2.4. Identify the modes of metal transfer used in MAGS welding activities, to include:</p> <ul style="list-style-type: none"> <li>• dip</li> <li>• spray</li> <li>• pulse</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables used in MAGS welding</p>	<p>3.1. Describe the importance of correct storage conditions for electrode wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrode wire, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• coated (copper)</li> </ul> <p>3.3. Describe the content and use of deoxidising agents added to electrode wires</p> <p>3.4. Describe the effects of using damaged or corroded electrode wires</p> <p>3.5. Identify the range and application of shielding gases and gas mixtures used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying out MAGS welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• shielding gas flow rate (LPM)</li> </ul>

Skills and Education Group Awards

<p>5. Know about material preparation and distortion control when using MAGS welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>
<p>6. Be able to complete welds in the overhead welding position (PE) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in MAGS welding activities</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the MAGS welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 14. Metal-Arc Gas Shielded Welding- (Overhead) – Stainless Steel

Unit References	K/618/0782
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying MAGS welding activities	<p>1.1. Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MAGS welding process</p>	<p>2.1. Identify the power sources used in MAGS welding</p> <p>2.2. Describe the principle of the self-adjusting arc mechanism as applied to MAGS welding</p> <p>2.3. Describe how inductance can regulate the quality of the weld deposit</p> <p>2.4. Identify the modes of metal transfer used in MAGS welding activities, to include:</p> <ul style="list-style-type: none"> <li>• dip</li> <li>• spray</li> <li>• pulse</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables used in MAGS welding</p>	<p>3.1. Describe the importance of correct storage conditions for electrode wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrode wire, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• coated (copper)</li> </ul> <p>3.3. Describe the content and use of deoxidising agents added to electrode wires</p> <p>3.4. Describe the effects of using damaged or corroded electrode wires</p> <p>3.5. Identify the range and application of shielding gases and gas mixtures used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying out MAGS welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding stainless steel in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• shielding gas flow rate (LPM)</li> </ul>

Skills and Education Group Awards

<p>5. Know about material preparation and distortion control when using MAGS welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>
<p>6. Be able to complete welds in the overhead welding position (PE) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in MAGS welding activities</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the MAGS welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 15. Metal-Arc Gas Shielded Welding – (Overhead) Aluminium

Unit References	M/618/0783
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying MAGS welding activities	<p>1.1. Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MAGS welding process</p>	<p>2.1. Identify the power sources used in MAGS welding</p> <p>2.2. Describe the principle of the self-adjusting arc mechanism as applied to MAGS welding</p> <p>2.3. Describe how inductance can regulate the quality of the weld deposit</p> <p>2.4. Identify the modes of metal transfer used in MAGS welding activities, to include:</p> <ul style="list-style-type: none"> <li>• dip</li> <li>• spray</li> <li>• pulse</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables used in MAGS welding</p>	<p>3.1. Describe the importance of correct storage conditions for electrode wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrode wire, to include:</p> <ul style="list-style-type: none"> <li>• non-coated</li> <li>• coated (copper)</li> </ul> <p>3.3. Describe the content and use of deoxidising agents added to electrode wires</p> <p>3.4. Describe the effects of using damaged or corroded electrode wires</p> <p>3.5. Identify the range and application of shielding gases and gas mixtures used in MAGS welding</p>
<p>4. Understand the welding parameters used when carrying out MAGS welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding aluminium in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• shielding gas flow rate (LPM)</li> </ul>

Skills and Education Group Awards

<p>5. Know about material preparation and distortion control when using MAGS welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>
<p>6. Be able to complete welds in the overhead welding position (PE) using the MAGS welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process on low carbon steel or stainless steel.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in MAGS welding activities</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the MAGS welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the MAGS welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 16. Tungsten-Arc Gas Shielded Welding – (Overhead) Low Carbon Steel

Unit References	A/618/0785
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out TAG welding activities	<p>1.1. Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with Health and Safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7. Describe the hazards associated when using the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• arc radiation</li> <li>• using high frequency</li> <li>• production of phosgene gas</li> </ul>
<p>2. Understand power sources and electrical features relating to the TAG welding process</p>	<p>2.1. Identify the power sources used in TAG welding</p> <p>2.2. Identify the type of welding current (AC/DC) and polarity to be used when welding:</p> <ul style="list-style-type: none"> <li>• low carbon steel</li> <li>• stainless steel</li> <li>• aluminium</li> </ul> <p>2.3. Describe the application and use of equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• high frequency unit</li> <li>• current control foot pedal</li> <li>• gas pressure regulator</li> <li>• gas flow meter</li> <li>• gas lens</li> </ul>

## Skills and Education Group Awards

<p>3. Understand the selection, composition, use and storage of welding consumables used in TAG welding</p>	<p>3.1. Describe the importance of correct storage conditions for tungsten electrodes and filler wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the range of different alloying elements added to tungsten electrodes</p> <p>3.3. Identify the electrode (tip) preparation required when using an AC or DC welding current</p> <p>3.4. Identify the content and application of a range of filler wires used in the TAG welding process</p> <p>3.5. Describe the effects of using damaged tungsten electrodes and filler wires</p> <p>3.6. Identify the range and application of shielding gases used in the TAG welding process</p>
<p>4. Understand the welding parameters used when carrying out TAG welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel, stainless steel or aluminium in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• slope in/slope out control</li> <li>• torch slope and tilt angles</li> <li>• high frequency</li> <li>• speed of travel</li> <li>• pre/post gas flow</li> <li>• shielding gas flow rate (LPM)</li> </ul> <p>4.2. Describe the application and function of gas backing /purging</p>

Skills and Education Group Awards

<p>5. Know about material preparation and distortion control when using TAG welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the main causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>
<p>6. Be able to complete welds in the overhead welding position (PE) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on one material type to cover, low carbon steel, stainless steel or aluminium in a thickness range of between 1.6 mm to 3 mm.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in TAG welding activities</p> <p>7.3. Describe the range and purpose for destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the TAG welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 17. Tungsten-Arc Gas Shielded Welding – (Overhead) Stainless Steel

Unit References	F/618/0786
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out TAG welding activities	<p>1.1 Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2 Identify the roles of various individuals involved with Health and Safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3 Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4 Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5 Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6 Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7 Describe the hazards associated when using the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• arc radiation</li> <li>• using high frequency</li> <li>• production of phosgene gas</li> </ul>
<p>2. Understand power sources and electrical features relating to the TAG welding process</p>	<p>2.1. Identify the power sources used in TAG welding</p> <p>2.2. Identify the type of welding current (AC/DC) and polarity to be used when welding:</p> <ul style="list-style-type: none"> <li>• low carbon steel</li> <li>• stainless steel</li> <li>• aluminium</li> </ul> <p>2.3. Describe the application and use of equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• high frequency unit</li> <li>• current control foot pedal</li> <li>• gas pressure regulator</li> <li>• gas flow meter</li> <li>• gas lens</li> </ul>
<p>3. Understand the selection, composition, use and storage of welding consumables used in TAG welding</p>	<p>3.1. Describe the importance of correct storage conditions for tungsten electrodes and filler wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the range of different alloying elements added to tungsten electrodes</p> <p>3.3. Identify the electrode (tip) preparation required when using an AC or DC welding current</p> <p>3.4. Identify the content and application of a range of filler wires used in the TAG welding process</p> <p>3.5. Describe the effects of using damaged tungsten electrodes and filler wires</p> <p>3.6. Identify the range and application of shielding gases used in the TAG welding process</p>

Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out TAG welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel, stainless steel or aluminium in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• slope in/slope out control</li> <li>• torch slope and tilt angles</li> <li>• high frequency</li> <li>• speed of travel</li> <li>• pre/post gas flow</li> <li>• shielding gas flow rate (LPM)</li> </ul> <p>4.2. Describe the application and function of gas backing /purgings</p>
<p>5. Know about material preparation and distortion control when using TAG welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the main causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>

Skills and Education Group Awards

<p>6. Be able to complete welds in the overhead welding position (PE) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on one material type to cover, low carbon steel, stainless steel or aluminium in a thickness range of between 1.6 mm to 3 mm.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>
<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in TAG welding activities</p> <p>7.3. Describe the range and purpose for destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the TAG welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 18. Tungsten-Arc Gas Shielded Welding – (Overhead) Aluminium

Unit References	K/618/0787
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the overhead (PE) welding position.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out TAG welding activities	<p>1.1. Identify the roles of various organisations involved with Health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with Health and Safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7. Describe the hazards associated when using the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• arc radiation</li> <li>• using high frequency</li> <li>• production of phosgene gas</li> </ul>
<p>2. Understand power sources and electrical features relating to the TAG welding process</p>	<p>2.1. Identify the power sources used in TAG welding</p> <p>2.2. Identify the type of welding current (AC/DC) and polarity to be used when welding:</p> <ul style="list-style-type: none"> <li>• aluminium</li> </ul> <p>2.3. Describe the application and use of equipment used in the TAG welding process, to include:</p> <ul style="list-style-type: none"> <li>• high frequency unit</li> <li>• current control foot pedal</li> <li>• gas pressure regulator</li> <li>• gas flow meter</li> <li>• gas lens</li> </ul>
<p>3. Understand the selection, composition, use and storage of welding consumables used in TAG welding</p>	<p>3.1. Describe the importance of correct storage conditions for tungsten electrodes and filler wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the range of different alloying elements added to tungsten electrodes</p> <p>3.3. Identify the electrode (tip) preparation required when using an AC or DC welding current</p> <p>3.4. Identify the content and application of a range of filler wires used in the TAG welding process</p> <p>3.5. Describe the effects of using damaged tungsten electrodes and filler wires</p> <p>3.6. Identify the range and application of shielding gases used in the TAG welding process</p>

Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out TAG welding in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel, stainless steel or aluminium in the overhead welding position (PE), to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• slope in/slope out control</li> <li>• torch slope and tilt angles</li> <li>• high frequency</li> <li>• speed of travel</li> <li>• pre/post gas flow</li> <li>• shielding gas flow rate (LPM)</li> </ul> <p>4.2. Describe the application and function of gas backing /purgings</p>
<p>5. Know about material preparation and distortion control when using TAG welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the main causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>

Skills and Education Group Awards

<p>6. Be able to complete welds in the overhead welding position (PE) using the TAG welding process</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the TAG welding process on one material type to cover, low carbon steel, stainless steel or aluminium in a thickness range of between 1.6 mm to 3 mm.</p> <ul style="list-style-type: none"> <li>• tee fillet (PE)</li> <li>• butt (PE)</li> <li>• open outside corner (PE)</li> <li>• lap joint (PE)</li> </ul> <p>6.3. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>
<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in TAG welding activities</p> <p>7.3. Describe the range and purpose for destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the TAG welding process</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the overhead position (PE) by the TAG welding process</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 19. Thick Plate Welding using Flux Cored Metal-Arc Gas Shielded Welding

Unit Reference	T/616/1300
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in the flat (PA) or horizontal vertical (PB) welding positions.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p> <p>Welds are produced by the metal-arc gas shielded (MAGS) welding process using flux cored wires. The material is low carbon steel in a range of thickness from 6 mm to 12 mm.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying MAGS welding activities using flux cored wires	<p>1.1. Identify the roles of various organisations involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an organisations Health and Safety Policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> </ul>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul>
<p>2. Understand power sources and electrical features relating to the MAGS welding process using flux cored wires</p>	<p>2.1. Identify the power sources used in MAGS welding using flux cored wires</p> <p>2.2. Describe the principle of the self-adjusting arc mechanism as applied to MAGS welding using flux cored wires</p> <p>2.3. Describe how inductance can influence the quality of the weld deposit</p> <p>2.4. Describe the characteristics of the mode of metal transfer, to include:</p> <ul style="list-style-type: none"> <li>• spray transfer</li> <li>• globular transfer</li> </ul>
<p>3. Understand the selection, use and storage of welding consumables</p>	<p>3.1. Describe the importance of correct storage conditions for flux cored electrode wires, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of flux cored wires</p> <p>3.3. Describe the content and use of fluxes added electrode wires</p> <p>3.4. Describe the effects of using damaged or corroded flux cored electrode wires</p> <p>3.5. Identify the range and application of shielding gases and gas mixtures used in flux cored MAGS welding</p>

Skills and Education Group Awards

<p>4. Understand the welding parameters used when carrying out MAGS welding using flux cored wires in the overhead welding (PE) position to produce butt and fillet welds</p>	<p>4.1. Identify and select the welding parameters to be used when welding low carbon steel in the flat (PA) or horizontal vertical (PB) welding positions, to include:</p> <ul style="list-style-type: none"> <li>• welding voltage range</li> <li>• welding amperage range</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• type of shielding gas (if used)</li> <li>• shielding gas flow rate (LPM)</li> </ul>
<p>5. Know about material preparation and distortion control when carrying out MAGS welding using flux cored wires</p>	<p>5.1. Identify suitable welding preparations for the type of joint and material thickness being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• shearing</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.3. Identify the main types of distortion found in completed welded joints, to include:</p> <ul style="list-style-type: none"> <li>• longitudinal</li> <li>• transverse</li> <li>• angular</li> </ul> <p>5.4. Identify the causes of distortion in welded joints</p> <p>5.5. Identify methods used to control distortion in welded joints</p> <p>5.6. Describe the significance of residual stress found in welded joints</p>
<p>6. Be able to complete welds in the flat (PA) or horizontal welding position (PB) by the MAGS welding process using flux cored wires</p>	<p>6.1. Identify appropriate safety checks on the welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints to be welded by the MAGS welding process using flux cored wires on low carbon steel in a thickness range of between 6 mm to 12 mm.</p> <ul style="list-style-type: none"> <li>• tee fillet (PA or PC)</li> <li>• single vee butt (PA)</li> <li>• double vee butt (PA)</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used in MAGS welding activities</p> <p>7.3. Describe the range and purpose for destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in welds produced by the MAGS welding process using flux cored wires</p>	<p>8.1. Identify defects and imperfections that may be found in welds completed in the flat (PA) or horizontal vertical position (PC) by the MAGS welding process using flux cored wires</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 20. Pipe Welding using Manual Metal-Arc Welding

Unit References	L/618/0788
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in pipe assemblies covering fixed and rotated welding positions.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p> <p>Welds will be produced in pipes of differing diameters and wall thicknesses.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out pipe welding activities	<p>1.1. Identify the roles of various organisations involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an Organisations health and safety policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7. Identify the risk associated with pipe welding on site, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• environmental (wind, rain etc.)</li> <li>• availability of power supply</li> <li>• working/welding in trenches</li> <li>• welding at heights</li> </ul>
<p>2. Understand power sources and electrical features relating to welding processes used for pipe welding activities</p>	<p>2.1. Identify the different power sources used when welding with MMA, MAGS and TAG welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• inverter</li> </ul> <p>2.2. Describe features of the power sources as listed in 2.1, to include:</p> <ul style="list-style-type: none"> <li>• type of current produced (AC/DC)</li> <li>• maintenance requirements</li> <li>• portability</li> <li>• suitable applications</li> </ul> <p>2.3. Identify specialist equipment used when carrying out pipe welding activities, to include:</p> <ul style="list-style-type: none"> <li>• pipe cutting equipment</li> <li>• jigs/fixtures</li> <li>• turntables/rotators/manipulators</li> </ul>

Skills and Education Group Awards

<p>3. Understand the selection, use and storage of welding consumables</p>	<p>3.1. Describe the importance of correct storage conditions for electrodes, wires and gas cylinders, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrodes, electrode wires and filler wires when carrying out pipe welding activities</p> <p>3.3. Describe the effects of using damaged or corroded electrodes, electrode wires and filler wires when carrying out pipe welding activities</p>
<p>4. Understand the welding parameters required when using MMA welding to produce welds in low carbon steel pipes</p>	<p>4.1. Identify and select the required welding parameters to be used when welding low carbon steel pipes using MMA welding processes, to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• welding current</li> <li>• electrode polarity</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• gas delay system</li> <li>• shielding gas type</li> <li>• shielding gas flow rate (LPM)</li> </ul>

<p>5. Know about material preparation and joint set-up when pipe welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint, diameter and wall thickness of the pipe being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Identify different types of joints used in pipe work assemblies, to include:</p> <ul style="list-style-type: none"> <li>• butt welds</li> <li>• branch joints</li> <li>• slip on flange</li> <li>• set on flange</li> </ul> <p>5.3. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.4. Identify the application of both permanent and temporary backing rings used in pipe welding</p> <p>5.5. Identify methods used to ensure pipe alignment before and during welding activities</p> <p>5.6. Identify different types of pipe work fittings, to include:</p> <ul style="list-style-type: none"> <li>• concentric reducers</li> <li>• eccentric reducers</li> <li>• equal diameter tee pieces</li> <li>• unequal diameter tee pieces</li> <li>• elbows 45° 60° 90°</li> <li>• blank ends (dished ends)</li> </ul>
<p>6. Be able to complete welds in pipe work using a selected welding process</p>	<p>6.1. Identify appropriate safety checks on the selected welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints (given in 6.3.) to be welded by one process from the following:</p> <ul style="list-style-type: none"> <li>• MMA welding</li> </ul> <p>6.3. Weld No 1 – single vee pipe butt weld – rotated. Weld No 2 – single vee pipe butt weld – fixed horizontal vertical position. Weld No 3 – pipe to flange weld – rotated. Weld No 4 – set on branch weld in unequal diameter pipes – rotated.</p> <p>6.4. Identify the practice of using dual process techniques for pipe welding activities</p>

Skills and Education Group Awards

	<p>6.5. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>
<p>7. Know the function of inspection, quality control and quality assurance as applied to pipe welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used for welding pipes</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> <li>• visual inspection of pipe bores/root penetration using endoscope/borescope</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in pipe welded joints produced by the MMA welding processes</p>	<p>8.1. Identify defects and imperfections that may be found in pipe welded assemblies using MMA welding processes</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 21. Pipe Welding using Metal-Arc Gas Shielded Welding

Unit References	R/618/0789
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in pipe assemblies covering fixed and rotated welding positions.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p> <p>Welds will be produced in pipes of differing diameters and wall thicknesses.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out pipe welding activities	<p>1.1. Identify the roles of various organisations involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an Organisations health and safety policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p>

Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• risk assessments</li> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7. Identify the risk associated with pipe welding on site, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• environmental (wind, rain etc.)</li> <li>• availability of power supply</li> <li>• working/welding in trenches</li> <li>• welding at heights</li> </ul>
<p>2. Understand power sources and electrical features relating to welding processes used for pipe welding activities</p>	<p>2.1. Identify the different power sources used when welding with MMA, MAGS and TAG welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• inverter</li> </ul> <p>2.2. Describe features of the power sources as listed in 2.1, to include:</p> <ul style="list-style-type: none"> <li>• type of current produced (AC/DC)</li> <li>• maintenance requirements</li> <li>• portability</li> <li>• suitable applications</li> </ul> <p>2.3. Identify specialist equipment used when carrying out pipe welding activities, to include:</p> <ul style="list-style-type: none"> <li>• pipe cutting equipment</li> <li>• jigs/fixtures</li> <li>• turntables/rotators/manipulators</li> </ul>

Skills and Education Group Awards

<p>3. Understand the selection, use and storage of welding consumables</p>	<p>3.1. Describe the importance of correct storage conditions for electrodes, wires and gas cylinders, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrodes, electrode wires and filler wires when carrying out pipe welding activities</p> <p>3.3. Identify the range and application of shielding gases and gas mixtures used when pipe welding with the MAGS welding process</p> <p>3.4. Describe the effects of using damaged or corroded electrodes, electrode wires and filler wires when carrying out pipe welding activities</p>
<p>4. Understand the welding parameters required when using MAGS welding to produce welds in low carbon steel pipes</p>	<p>4.1. Identify and select the required welding parameters to be used when welding low carbon steel pipes using MAGS welding processes, to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• welding current</li> <li>• electrode polarity</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• gas delay system</li> <li>• shielding gas type</li> <li>• shielding gas flow rate (LPM)</li> </ul>
<p>5. Know about material preparation and joint set-up when pipe welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint, diameter and wall thickness of the pipe being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Identify different types of joints used in pipe work assemblies, to include:</p> <ul style="list-style-type: none"> <li>• butt welds</li> <li>• branch joints</li> <li>• slip on flange</li> <li>• set on flange</li> </ul> <p>5.3. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.4. Identify the application of both permanent and temporary backing rings used in pipe welding</p> <p>5.5. Identify methods used to ensure pipe alignment before and during welding activities</p> <p>5.6. Identify different types of pipe work fittings, to include:</p> <ul style="list-style-type: none"> <li>• concentric reducers</li> <li>• eccentric reducers</li> <li>• equal diameter tee pieces</li> <li>• unequal diameter tee pieces</li> <li>• elbows 45° 60° 90°</li> <li>• blank ends (dished ends)</li> </ul>
<p>6. Be able to complete welds in pipe work using a selected welding process</p>	<p>6.1. Identify appropriate safety checks on the selected welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints (given in 6.3.) to be welded by one process from the following:</p> <ul style="list-style-type: none"> <li>• MAGS welding</li> </ul> <p>6.3. Weld No 1 – single vee pipe butt weld – rotated. Weld No 2 – single vee pipe butt weld – fixed horizontal vertical position. Weld No 3 – pipe to flange weld – rotated. Weld No 4 – set on branch weld in unequal diameter pipes – rotated.</p> <p>6.4. Identify the practice of using dual process techniques for pipe welding activities</p> <p>6.5. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to pipe welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used for welding pipes</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> <li>• visual inspection of pipe bores/root penetration using endoscope/borescope</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in pipe welded joints produced by the MAGS welding processes</p>	<p>8.1. Identify defects and imperfections that may be found in pipe welded assemblies using MAGS welding processes</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## 22. Pipe Welding using Tungsten-Arc Gas Shielded Welding

Unit References	J/618/0790
Level	3
Credit Value	7
Guided Learning Hours	60
Unit Summary	<p>Learners will develop a high standard of practical skills to enable them to produce acceptable welded joints in pipe assemblies covering fixed and rotated welding positions.</p> <p>This Diploma level qualification requires the learner to have a good understanding of health and safety, welding equipment, consumables, joint preparation and the quality assurance required to conform to relevant standards applicable to the welding industry.</p>
Learning Outcomes The learner will:	<p>Assessment Criteria The learner can:</p>
1. Know about Health and Safety when carrying out pipe welding activities	<p>1.1. Identify the roles of various organisations involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Health and Safety Executive (HSE)</li> <li>• Environmental Health</li> <li>• Local Authorities</li> </ul> <p>1.2. Identify the roles of various individuals involved with health and safety in the workplace, to include:</p> <ul style="list-style-type: none"> <li>• Company safety officers</li> <li>• Company safety representatives</li> <li>• Environmental health officers</li> <li>• HSE inspectors</li> </ul> <p>1.3. Identify the purpose and typical contents of an Organisations health and safety policy</p> <p>1.4. Describe the purpose of a risk assessment, to include:</p> <ul style="list-style-type: none"> <li>• who should carry out risk assessments</li> <li>• when to carry out a risk assessment</li> <li>• identification of the 5 steps of risk assessment</li> </ul> <p>1.5. Identify the precautions to be taken when working in high risk areas, to include:</p> <ul style="list-style-type: none"> <li>• risk assessments</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• permits to work</li> <li>• high/low temperature working conditions</li> <li>• lock off systems</li> <li>• isolation of equipment</li> </ul> <p>1.6. Describe the control and safe removal of welding fumes and gases created during the welding process, to include:</p> <ul style="list-style-type: none"> <li>• natural extraction</li> <li>• local extraction</li> <li>• PPE and specialist breathing equipment</li> </ul> <p>1.7. Identify the risk associated with pipe welding on site, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• environmental (wind, rain etc.)</li> <li>• availability of power supply</li> <li>• working/welding in trenches</li> <li>• welding at heights</li> </ul>
<p>2. Understand power sources and electrical features relating to welding processes used for pipe welding activities</p>	<p>2.1. Identify the different power sources used when welding with TAG welding, to include:</p> <ul style="list-style-type: none"> <li>• transformer</li> <li>• generator</li> <li>• rectifier</li> <li>• inverter</li> </ul> <p>2.2. Describe features of the power sources as listed in 2.1, to include:</p> <ul style="list-style-type: none"> <li>• type of current produced (AC/DC)</li> <li>• maintenance requirements</li> <li>• portability</li> <li>• suitable applications</li> </ul> <p>2.3. Identify specialist equipment used when carrying out pipe welding activities, to include:</p> <ul style="list-style-type: none"> <li>• pipe cutting equipment</li> <li>• jigs/fixtures</li> <li>• turntables/rotators/manipulators</li> </ul>

Skills and Education Group Awards

<p>3. Understand the selection, use and storage of welding consumables</p>	<p>3.1. Describe the importance of correct storage conditions for electrodes, wires and gas cylinders, to include:</p> <ul style="list-style-type: none"> <li>• location</li> <li>• ventilation</li> <li>• contamination</li> <li>• labelling</li> </ul> <p>3.2. Identify the use of different types of electrodes, electrode wires and filler wires when carrying out pipe welding activities</p> <p>3.3. Identify the range and application of shielding gases and gas mixtures used when pipe welding with the MAGS or TAG welding process</p> <p>3.4. Describe the effects of using damaged or corroded electrodes, electrode wires and filler wires when carrying out pipe welding activities</p>
<p>4. Understand the welding parameters required when using TAG welding to produce welds in low carbon steel pipes</p>	<p>4.1. Identify and select the required welding parameters to be used when welding low carbon steel pipes using TAG welding processes, to include:</p> <ul style="list-style-type: none"> <li>• welding voltage</li> <li>• welding current</li> <li>• electrode polarity</li> <li>• wire feed speed</li> <li>• torch slope and tilt angles</li> <li>• electrode extension</li> <li>• speed of travel</li> <li>• inductance</li> <li>• gas delay system</li> <li>• shielding gas type</li> <li>• shielding gas flow rate (LPM)</li> </ul>
<p>5. Know about material preparation and joint set-up when pipe welding</p>	<p>5.1. Identify suitable welding preparations for the type of joint, diameter and wall thickness of the pipe being welded, to include:</p> <ul style="list-style-type: none"> <li>• included angle</li> <li>• angle of bevel</li> <li>• root face dimension</li> <li>• root gap dimension</li> </ul> <p>5.2. Identify different types of joints used in pipe work assemblies, to include:</p> <ul style="list-style-type: none"> <li>• butt welds</li> <li>• branch joints</li> <li>• slip on flange</li> <li>• set on flange</li> </ul> <p>5.3. Describe the advantages and limitations of the methods listed that are used to produce suitable welding preparations on materials, to include:</p> <ul style="list-style-type: none"> <li>• thermal methods</li> <li>• mechanical (chip forming)</li> </ul>

## Skills and Education Group Awards

	<ul style="list-style-type: none"> <li>• bevelling machines</li> <li>• abrasive methods</li> </ul> <p>5.4. Identify the application of both permanent and temporary backing rings used in pipe welding</p> <p>5.5. Identify methods used to ensure pipe alignment before and during welding activities</p> <p>5.6. Identify different types of pipe work fittings, to include:</p> <ul style="list-style-type: none"> <li>• concentric reducers</li> <li>• eccentric reducers</li> <li>• equal diameter tee pieces</li> <li>• unequal diameter tee pieces</li> <li>• elbows 45° 60° 90°</li> <li>• blank ends (dished ends)</li> </ul>
<p>6. Be able to complete welds in pipe work using a selected welding process</p>	<p>6.1. Identify appropriate safety checks on the selected welding equipment prior to use</p> <p>6.2. Select suitable welding parameters to enable the listed joints (given in 6.3.) to be welded by one process from the following:</p> <ul style="list-style-type: none"> <li>• TAG welding</li> </ul> <p>6.3. Weld No 1 – single vee pipe butt weld – rotated. Weld No 2 – single vee pipe butt weld – fixed horizontal vertical position. Weld No 3 – pipe to flange weld – rotated. Weld No 4 – set on branch weld in unequal diameter pipes – rotated.</p> <p>6.4. Identify the practice of using dual process techniques for pipe welding activities</p> <p>6.5. Carry out destructive tests on the completed welds and document the results. Tests to include:</p> <ul style="list-style-type: none"> <li>• face bend</li> <li>• root bend</li> <li>• fracture test</li> <li>• nick break test</li> </ul>

## Skills and Education Group Awards

<p>7. Know the function of inspection, quality control and quality assurance as applied to pipe welding activities</p>	<p>7.1. Identify the function of:</p> <ul style="list-style-type: none"> <li>• weld inspection activities</li> <li>• quality control</li> <li>• quality assurance</li> </ul> <p>7.2. Describe the importance of carrying out quality control checks on consumables used for welding pipes</p> <p>7.3. Describe the range and purpose of destructive tests used on welded joints</p> <p>7.4. Identify the use and application of the four main methods of non-destructive testing (NDT), to include:</p> <ul style="list-style-type: none"> <li>• dye penetrant flaw detection</li> <li>• magnetic particle flaw detection</li> <li>• ultrasonic flaw detection</li> <li>• radiographic flaw detection using both X ray and gamma ray</li> <li>• visual inspection of pipe bores/root penetration using endoscope/borescope</li> </ul> <p>7.5. Identify the importance of documenting weld inspection activities</p>
<p>8. Know about defects found in pipe welded joints produced by the TAG welding processes</p>	<p>8.1. Identify defects and imperfections that may be found in pipe welded assemblies using MMA, MAGS and TAG welding processes</p> <p>8.2. Identify aids used when carrying out visual inspection of welded joints, to include:</p> <ul style="list-style-type: none"> <li>• magnifying glass</li> <li>• welding gauge</li> <li>• fillet weld gauge</li> <li>• borescope</li> </ul>

## Appendices

---

### Recognition of Prior Learning, Exemption and Credit Transfer

---

Skills and Education Group Awards policy enables learners to avoid duplication of learning and assessment in a number of ways:

- Recognition of Prior Learning (RPL) – a method of assessment that considers whether a learner can demonstrate that they can meet the assessment requirements for a unit through knowledge, understanding or skills they already possess and do not need to develop through a course of learning.
- Exemption - Exemption applies to any certificated achievement which is deemed to be of equivalent value to a unit within Skills and Education Group Awards qualification but which does not necessarily share the exact learning outcomes and assessment criteria. It is the assessor's responsibility, in conjunction with the Internal Moderator, to map this previous achievement against the assessment requirements of the Skills and Education Group Awards qualification to be achieved in order to determine its equivalence.

Any queries about the relevance of any certificated evidence, should be referred in the first instance to your centre's internal moderator and then to Skills and Education Group Awards.

It is important to note that there may be restrictions upon a learner's ability to claim exemption or credit transfer which will be dependent upon the currency of the unit/qualification and a learner's existing levels of skill or knowledge.

Where past certification only provides evidence that could be considered for exemption of part of a unit, learners must be able to offer additional evidence of previous or recent learning to supplement their evidence of achievement.

- Credit Transfer – Skills and Education Group Awards may attach credit to a qualification, a unit or a component. Credit transfer is the process of using certificated credits achieved in one qualification and transferring that achievement as a valid contribution to the award of another qualification. Units / Components transferred must share the same learning outcomes and assessment criteria along with the same unit number. Assessors must ensure that they review and verify the evidence through sight of:
  - original certificates OR
  - copies of certificates that have been signed and dated by the internal moderator confirming the photocopy is a real copy and make these available for scrutiny by the External Moderator.
- Equivalencies – opportunities to count credits from the unit(s) from other qualifications or from unit(s) submitted by other recognised organisations towards the place of mandatory or optional unit(s) specified in the rule of combination. The unit must have the same credit value or greater than the unit(s) in question and be at the same level or higher.

Skills and Education Group Awards encourages its centres to recognise the previous achievements of learners through RPL, Exemption and Credit Transfer. Prior achievements may have resulted from past or present employment, previous study or voluntary activities.

## Skills and Education Group Awards

Centres should provide advice and guidance to the learner on what is appropriate evidence and present that evidence to the external moderator in the usual way.

Further guidance can be found in 'Delivering and Assessing Skills and Education Group Awards Qualifications' which can be downloaded from:

[https://skillsandeducationgroupawards.co.uk/wp-content/uploads/2017/12/SEG-Awards\\_Delivering-and-Assessing-Qualifications-19-20.pdf](https://skillsandeducationgroupawards.co.uk/wp-content/uploads/2017/12/SEG-Awards_Delivering-and-Assessing-Qualifications-19-20.pdf)

### **Certification**

---

Learners will be certificated for all units and qualifications that are achieved and claimed.

Skills and Education Group Awards policies and procedures are available on the Skills and Education Group Awards website.

## **Glossary of Terms**

---

### **Guided Learning Hours (GLH)**

GLH is where the learner participates in education or training under the immediate guidance or supervision of a tutor (or other appropriate provider of education or training). It may be helpful to think – ‘Would I need to plan for a member of staff to be present to give guidance or supervision?’

GLH is calculated at the unit/component level and added up at the qualification level.

Examples of guided learning include:

- Face-to-face meeting with a tutor
- Telephone conversation with a tutor
- Instant messaging with a tutor
- Taking part in a live webinar
- Classroom-based instruction
- Supervised work
- Taking part in a supervised or invigilated assessment
- The learner is being observed.

### **TQT (Total Qualification Time)**

The number of notional hours which represents an estimate of the total amount of time that could reasonably be expected to be required, in order for a learner to achieve and demonstrate the achievement of the level of attainment necessary for the award of a qualification.’ The size of a qualification is determined by the TQT.

TQT is made up of the GLH plus all other time taken in preparation, study or any other form of participation in education or training but not under the direct supervision of a lecturer, supervisor or tutor.

TQT is calculated at qualification level and not unit/component level.

Examples of unsupervised activities that could contribute to TQT include:

- Researching a topic and writing a report
- Watching an instructional online video at home/e-learning
- Watching a recorded webinar
- Compiling a portfolio in preparation for assessment
- Completing an unsupervised practical activity or work
- Rehearsing a presentation away from the classroom
- Practising skills unsupervised
- Requesting guidance via email – will not guarantee an immediate response.